

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY  
CONDITION CERTIFICATE

No : 215Date : 31/3/19It is certified that an inspection team headed by Talendra Debata.Junior Engineer P.H. Section-II, Talcher (Name of Officer  
with designation) from Junior Engineer P.H. Sec-II, Talcher (Name of  
Department/Office) inspected the St. Johns School, Angara,Near BSNL Office, Talcher; (Name & Address of  
the School) on 31-03-19 and found that theSt. Johns School Angara near BSNL Office Talcher (Name of School) has safe  
drinking water facilities for the students and members of staff of the institution and  
is maintaining the hygienic sanitation condition in the school building & the  
campus as per the norms prescribed by the Central/State/U.T. Govt.

The above valid for a period of \_\_\_\_\_

Signature with Seal: [Signature]Name Talendra Debata 31.3.19Designation Junior Engineer P.H. Section-II, Talcher

To,

St. Johns School Angara  
Near BSNL office Talcher  
Dt. Angul Odisha

(Name &amp; Address of the Institution)